




From: Dave Larsen <dlarsen@reiengineering.com>
Sent: Tuesday, July 02, 2019 8:29 AM
To: Stoltz, Carrie R - DNR
Subject: Tower
Attachments: REI_20190702_082633.pdf


Looks like I forgot to include this attachment also. This is from 1997 and just a quick, not to scale, drawing of Geoprobe boring placements. Main point of this is the location of the Drake boring (B-4). Again, Drake report documented a UST with 20+ holes in it, DRO water of 490,000 ppm at GP1 and a basement that flooded and was filled with petroleum odors over a year after the UST was removed.

Thank you,
David N. Larsen P.G.
Senior Hydrogeologist / Professional Geologist



Connect with us :   

Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.



ALL MEASUREMENTS ON BACK